

CG 2-11S型 大管径手摇切割机零部件报价单

上海华威焊割机械有限公司

Part No.	Description	Number	Note	Part No.	Description	Number	Note
PC22-001	Machine base	1		PC22-034	Oxygen hose	2	
PC22-002	Guide wheel assembly	4		PC22-035	Acetylene hose	1	
PC22-003	Guide wheel	4		PC22-036	Big wing bolt	1	
PC22-004	Guide wheel axile	4		PC22-037	big flat washer	2	
PC22-005	Guide wheel gland	4		PC22-038	Beam plate	1	
PC22-006	guide wheel shaft bush	4		PC22-039	Vertical adjusting screw shaft	1	
PC22-007	Rack bar locating pin	1		PC22-040	Chain(Standard for Ø1m Pipe)		
PC22-008	Cross rack bar	1		PC22-041	Bracket	1	
PC22-009	Bracket shaft	2		PC22-042	Sprocket shaft bush	1	
PC22-010	Bracket shaft sleeve	2		PC22-043	Big worm	1	
PC22-011	Small handle unit	2		PC22-044	Worm spacer	1	
PC22-012	Handle shaft	2		PC22-045	Bear gasket	1	
PC22-013	Handle shaft cap	2		PC22-046	Clutch taper	6	
PC22-014	small handwheel	2		PC22-047	Sprocket	1	
PC22-015	Torch holder assembly	1		PC22-048	Clutch	1	
PC22-016	Torch holder	1		PC22-049	Sprocket Shaft	1	
PC22-017	Holder connection	1		PC22-050	Worm shaft of hand crank unit	1	
PC22-018	Cross rack bar holder	1		PC22-051	Worm	1	
PC22-019	Torch and pipeline assembly	1		PC22-052	Worm Front block stop	1	
PC22-020	Torch unit	1		PC22-053	Worm rear block stop	1	
PC22-021	Torch	1		PC22-054	Crank	2	
PC22-022	Torch nut	1		PC22-055	Handle	2	
PC22-023	Torch rack	1		PC22-056	Clutch shifting yoke assembly	1	
PC22-024	Gas distributor	1		PC22-057	Yoke front block stop	1	
PC22-025	Inlet connection	2		PC22-058	Yoke rear block stop	1	
PC22-026	Oxygen connection nut	1		PC22-059	Shift yoke	1	
PC22-027	Acetylene connection nut	1		PC22-060	shift yoke shaft	1	
PC22-028	Preheat Oxygen valve needle	1		PC22-061	Shift block	2	
PC22-029	Preheat oxygen valve body	1		PC22-062	Yoke gear	1	
PC22-030	Cutting oxygen valve body	1		PC22-063	Yoke gear shaft	1	
PC22-031	Cutting oxygen valve needle	1		PC22-064	Clutch handle	1	
PC22-032	Acetylene valve body	1		PC22-065	Brand	1	
PC22-033	Acetylene valve needle	1		PC22-066	Spare big guide wheel	4	

Part No.	Description	Number	Note	Part No.	Description	Number	Note
PC22-101	Flat washer Ø5			PC22-116	Inner hexagonal screw M8x16		
PC22-102	Wing bolt M5x20	1		PC22-117	Outer snap spring Ø10		
PC22-103	Socket cap screw M5x12			PC22-118	Socket cap screw M6x60		
PC22-104	Bear 6001	8		PC22-119	Half-round head nut M5		
PC22-105	Inter snap spring Ø28	4		PC22-120	Inner hexagonal screw M6x25		
PC22-106	Half sunk screw 5x12			PC22-121	Elastic straight pin Ø4x20		
PC22-107	Flat washer Ø12			PC22-122	Socket cap screw M6x12		
PC22-108	Hexagonal nut M12	8		PC22-123	Socket cap screw M5x8		
PC22-109	Wing bolt M6x15	4		PC22-124	Steel ball Ø6		
PC22-110	Washer Ø6			PC22-125	Spring Ø6x12		
PC22-111	Elastic straight pin Ø2.5x18			PC22-126	Locking screw M8x8		
PC22-112	Socket cap M6x20			PC22-127	Bear 6002	4	
PC22-113	Socket cap M3x6			PC22-128	Spring Ø7x22		
PC22-114	Rivot Ø2			PC22-129	Outer snap ring Ø4		
PC22-115	Spring Ø32x60	1		PC22-130	Elastic straight pin Ø2.5x12		